P.01

E	QUIPMENT	LIST AND	WEIGHT	AND	BALANCE	REVISIO	NC	
MAKE: Pipe	EMODI	SL: PA-28	-140 :	5/N;c	28-225	18 1	N: 4180	
Empty weig records.	ht condit	tion befo	re equip	pment	change	as per	aircraft	
EMPTY WEIG	HT: 1284	7 marca.	8525	MONDA	MTG . 100	7 = 20 1.5		

~ /

DAD: 365,3	LI LWCG: DOAD	MOMENTS: 109,520.68 USEFUL
QUIPMENT REMOVED: ITEM Hat Rock	S/N	WEIGHT X ARM = MOMENT 2.5 136.6 341.50
•		
·		
		MOMENTS 109/179, 18 SEFUL LOAD 84
JIPMENT INSTALLE	D:	
ITEM	S/N	WEIGHT X ARM = MOMENT
MKI2D KMA 24	06262	5.7 59.4 338 57
KR 84	17844	1.5 64.4 96.60

S/N: 28-22518 N: 4180 J

3. TO 824	011101		<u>e1.</u>	
3. 10007	29936		45.3	38.17
4. KR 8lg	17844	1.5	64.4	96.60
5. KA42B	7873	2.4	1149	275.76
6. CI 102		-6	16.	69.60
7. 10338	P-18811-0	1.12	666	74.59
8. Roll Servo	8242A	2.3	142	326.60
9. Cables		.5	104.3	52,15
10. Nose Wheel Fairi	ng	3.3	34.3	113,19
11. Main Wheel Fairin	A	7.4	109.6	811.04
12. Hat Rack	0	13.5	136.6	1844.10
13				
14.				
15				

Empty weight condition after equipment revision: EMPTY WEIGHT 1323.12 EWCG 55.67 MOMENTS 113349.64 USEFUL LOAD \$26.88

It is the pilots or operators responsibility to insure the proper loading of the aircraft in accordance with current weight and balance data. DATE 7-12-00

071- 88+ @ 15# gas Ignel 2 6#

LAMP AVIATION SERVICE, INC. 257 AIRPORT RD. CARROLLTON, OHIO 44615